Water Testing Results - Pleasant Hill School District
Action Level is 15 parts per billion (ppb)

Fixture Location / Description	Fixture ID #	Test Date	Test Results (ppb)	
PHES 2nd Floor Hall Staff Upper Drinking Fountain	20810100-023DW	6/16/2021	ND	
PHES 2nd Floor Hall Staff Lower Drinking Fountain	20810100-024DW	6/16/2021	ND	
PHES 3rd Floor Hallway Girl's Restroom North Sink	20810100-068BF	6/16/2021	ND	
PHES 3rd Floor Hallway Girl's Restroom Center North Sink	20810100-069BF	6/16/2021	2.21	
PHES 3rd Floor Hallway Girl's Restroom Center South Sink	20810100-070BF	6/16/2021	ND	
PHES 3rd Floor Hallway Girl's Restroom South Sink	20810100-071BF	6/16/2021	ND	
PHES 3rd Floor Hallway Boy's Restroom North Sink	20810100-072BF	6/16/2021	3.76	
PHES 3rd Floor Hallway Boy's Restroom Center North Sink	20810100-073BF	6/16/2021	2.22	
PHES 3rd Floor Hallway Boy's Restroom Center South Sink	20810100-074BF	6/16/2021	ND	
PHES 3rd Floor Hallway Boy's Restroom South Sink	20810100-075BF	6/16/2021	ND	
PHES Staff Room Instant Hot Water Tap	20810100-095OT	6/16/2021	ND	
PHES Gym Girl's Restroom Center East Sink	20810102-004BF	6/16/2021	8.27	
PHES Gym Girl's Restroom Center West Sink	20810102-005BF	6/16/2021	ND	
PHES Gym Boy's Restroom Center East Sink	20810102-008BF	6/16/2021	ND	
PHES Gym Boy's Restroom Center West Sink	20810102-009BF	6/16/2021	2.61	
PHHS Laundry Room Ice Machine	20810201-020IM	6/16/2021	ND	
PHHS Gym Commons Water Bottle Filler	20810201-052WB	6/16/2021	5.89	
PHHS Band Room Drinking Fountain	20810202-002DW	6/16/2021	ND	
PHHS Choir Room Water Bottle Filler	20810202-003WB	6/16/2021	ND	
PHHS Choir Room Drinking Fountain	20810202-004DW	6/16/2021	ND	
PHHS General Purpose Room Drinking Fountain	20810202-012DW	6/16/2021	ND	
PHHS Aux Gym Upper Drinking Fountain	20810203-002DW	6/16/2021	ND	
PHHS Aux Gym Lower Drinking Fountain	20810203-003DW	6/16/2021	ND	
ND = Not Dectected - Lead level is below the set detection limits of 2 ppb				

Water Testing Results - Pleasant Hill School District Action Level is 15 parts per billion (ppb)					
Fixture Location / Description	Fixture ID #	Test Date	Test Results (ppb)		
PHHS Aux Gym Girl's Restroom West Sink	20810203-005BF	6/16/2021	ND		
PHHS Aux Gym Boy's Restroom East Sink	20810203-006BF	6/16/2021	ND		
PHHS Aux Gym Water Bottle Filler	20810203-010WB	6/16/2021	ND		
PHHS Wood Shop Drinking Fountain	20810204-012DW	6/16/2021	5.07		

ND = Not Dectected - Lead level is below the set detection limits of 2 ppb