

**Water Testing Results - Pleasant Hill School District**  
**Action Level is 15 parts per billion (ppb)**

<b>Fixture Location / Description</b>	<b>Fixture ID #</b>	<b>Test Date</b>	<b>Test Results (ppb)</b>
District Office Kitchen Sink	20810000-001KF	5/5/2021	3.38
District Office Restroom Sink	20810000-002BF	5/5/2021	ND
Paint Shop Restroom Sink	20810002-001BF	5/5/2021	ND
Bus Barn Women's Restroom Sink	20810003-001BF	5/5/2021	7.66
Bus Barn Men's Restroom Sink	20810003-002BF	5/5/2021	3.65
PHES North (Blue) Gym - East Drinking Fountain	20810101-001DW	5/5/2021	5.67
PHES North (Blue) Gym - Boy's Locker Room Sink	20810101-003OT	5/5/2021	3.37
PHES North (Blue) Gym - Boy's Locker Room Drinking Fountain	20810101-004DW	5/5/2021	2.91
PHES North (Blue) Gym - Girl's Locker Room Sink	20810101-005OT	5/5/2021	3.04
PHES North (Blue) Gym - Girl's Locker Room Drinking Fountain	20810101-006DW	5/5/2021	2.21
PHES North (Blue) Gym - Boy's Restroom East Sink	20810101-007BF	5/5/2021	ND
PHES North (Blue) Gym - Boy's Restroom West Sink	20810101-008BF	5/5/2021	2.27
PHES North (Blue) Gym - Girl's Restroom South Sink	20810101-009BF	5/5/2021	ND
PHES North (Blue) Gym - Girl's Restroom North Sink	20810101-010BF	5/5/2021	4.87
PHES Wrestling Room - Canteen Drinking Fountain	20810105-001DW	5/5/2021	49.2
PHES Wrestling Room - Canteen Sink	20810105-002KF	5/5/2021	ND
PHES Music Building Sink	20810108-001CF	5/5/2021	6.19
PHES Library - West Drinking Fountain	20810109-001DW	5/5/2021	43.1
PHES Library - West Sink	20810109-002OT	5/5/2021	13.6
Community Center - Kitchen Sink	20810110-001KF	5/5/2021	ND
Community Center - Drinking Fountain	20810110-002DW	5/5/2021	ND
Community Center - Boy's Restroom North Sink	20810110-003BF	5/5/2021	ND
Community Center - Boy's Restroom South Sink	20810110-004BF	5/5/2021	ND
Community Center - Girl's Restroom West Sink	20810110-005BF	5/5/2021	ND
Community Center - Girl's Restroom East Sink	20810110-006BF	5/5/2021	2.7

ND = Not Detected - Lead level is below the set detection limits of 2 ppb